

## PULL OUT TORQUE CURVE OF 42HT64-5003S

Microstep : 1000  
Current :5A

AC 220V

